

TREADLINE

CLEANING & MAINTENANCE

Preventative Maintenance

- To ensure effective slip-resistance and optimum step edge definition is maintained, remove accumulative dirt and grease from the walking surface at regular intervals.
- Cleaning should be by gentle scrubbing with a solution of proprietary floor detergent and warm water. The aluminium may be buffed using a fine grade steel work.

Daily Cleaning

•	Sweep the area daily and spot clean any obvious marks or gr
	ease spots with a neutral cleaner and warm water. Dry
	thoroughly before allowing traffic on the staircase.

ARTECH SYSTEMS